

****spare part**** MICROMASTER 440 without filter 380-480 V 3 AC
+10/-10% 47-63 Hz constant torque 3 kW overload 150% 60 s,
200% 3 s square-law torque 3 kW 202x 149x 172 (HxWxD) degree
of protection IP20 ambient temperature -10+50 °C without
AOP/BOP

Дополнительная информация

Industry Online Support (Руководства, Каталоги, Сертификаты, FAQ, ...)
<https://support.industry.siemens.com/cs/products?mfn=ps&lc=en-WW>
Industry Mall (Каталог и система обработки заказов)
<https://mall.industry.siemens.com>

