

****spare part**** MICROMASTER 440 without filter 380-480 V 3 AC +10/-10% 47-63 Hz constant torque 110 kW overload 136% 57 s, 160% 3s square-law torque 132 kW 1400x 326x 356 (HxWxD) degree of protection IP20 ambient temperature 0° - 40 °C without AOP/BOP

Дополнительная информация

Industry Online Support (Руководства, Каталоги, Сертификаты, FAQ, ...)
<https://support.industry.siemens.com/cs/products?mfn=ps&lc=en-WW>
Industry Mall (Каталог и система обработки заказов)
<https://mall.industry.siemens.com>

